
Attachment to Oct. 2, 1998 1&E of Surface Management notice (se.... no. UTU 66357) -Photographs (enclosed with attachment in a page size plastic enclosure). The reverse of photos and panorama are marked with the serial number, date, and numbering as below. Descriptions are as follows


Photo 1 - (wide angle) view to west (from eastern-most end of project area) showing natural revegetation in center to left (area stripped of top soil, at right - red arrow). Miscl. equipment is about (green arrow at left and blue arrow at right). Master power switch is at base of transformer pole at left (purple arrow). Closer view of equipment (brown arrows at center) are shown in photos 2 and 3.


Photo 2 - (wide angle) view to NNE of inactive placer processing equipment and facilities: 1-settling pond, 2 - wooden structure housed fine gold recovery equipment (note doors are open), 3 - electrical panel and knudson bowl piece of equipment, 4 - wet screen, and 5 - grizzly screen for initial screening-out of oversized material, moved into stockpile 6). Note gap of equipment between items 3 and 4. Pipe rack type piece of equipment is at far left.

Photo 3 - (wide angle) view to north of some of same items in photo 2 with addition of wet loading hopper (black arrow at right). Finer material that fell through grizzly screen (item 5 in photo 2) would be loaded into this hopper which has water spray bars inside.


Photo 4 - view to west of wash-out in access road (at left, green arrow). Vehicular traffic has been driving around wash-out at right (red arrow).











10 886 8022-1-2 N N-16 2

PHOTO 1 OCT 2 1998 14 F.

VTU 66357

13.1% pyloto 9

18 886 9522-1-2 N H-12 Z

PHOTO 3

15 886 8522-1-2 N N-12 Z

26 NION NIZZ-1-Z N N-14 Z

BCH PHOPOS

PHOTO 4

Attachment to Oct. 2, 1998 I&E of Surface Management notice (serial no. UTU 66354) -- The general location of the photographer and angle of the photo is on the opposite side of this page; the reverse of the photo is marked with the serial number, date, and numbering below).

Photo 1 - [wide angle] view to NNW of unreclaimed disturbances in the south-central part of the project area (old placer plant was set up to left of posts (green arrows), oversized stockpiles are at right (red arrows) and old settling pond was at left (black arrow). Compare with left-hand side of panorama 1 from Oct. 20, 1997 inspection.



